



THE
PRESIDENTIAL
TOWER
★★★★★



CNTC HONG KONG

CONSTRUCTION

Update (March 2026)

WWW.THEPRESIDENTIALTOWER.CO.IN



THE PRESIDENTIAL TOWER

The Presidential Tower is the tallest residential tower of Bengaluru that incorporates an exquisite blend of infinite opulence and panoramic vistas sprawling along the land area of approx. 5 acres. Each floor features eight spacious, well-lit, thoughtfully designed, and naturally ventilated 3 & 4 bed residencies.

Are you ready to experience a life full of fascinating retreat with jaw-breaking celestial views everyday? Claim your bespoke luxury residence today!



1. Entrance Arch work in progress



2. Visitor car parking lawn work in progress



3. East Side Landscape work in progress



4. South East Side landscape plastering work is progress



5. Granite flooring work in progress



6. Facade ACP paneling work in progress



7. Facade glass fixing work in progress



8. Granite flooring work in progress



9. Granite coping work in progress



10. Pavers work in progress



11. Crazy flooring tiles laying work in progress



12. Podium ramp north side waterproofing protection screed concrete work in progress



13. West side Clara paint work in progress



14. Block work in progress at s/e compound



15. PHE panel 240 sqm cable laying work in progress



16. Pcc work in progress at landscape area



17. Drain laying near transformer yard



18. Column & slab removed from staircase at south side



19. Month of March 2026 Tower A Marble laying completed flats



PA 1301



PA 1302



PA 1401



PA 1601



PA 1804



PA 2001



PA 2002



PA 2004



PA 2102



PA 2202

20. Month of March 2026 Tower A Marble laying completed flats



PA 2501



PA 2502



PA 2504



PA 2901



PA 3102



PA 3202



PA 3203



PA 3204



PA 3302

21. Month of March 2026 Tower B Marble laying completed flats



PB 601



PB 803



PB 1001



PB 1102



PB 1103



PB 1104



PB 1201



PB 1202



PB 1203



PB 1503

22. Month of March 2026 Tower B Marble laying completed flats

23. Tower A 4501 flat block work measuring with QS



PB 1504



PB 2203



PB 2304



PB 2402



24. Health club 2x4 marble laying work in progress



25. Basement -2 IPS finishing work in progress



26. 153 mtr level railing work in progress



27. Tower A west side IMR railing work in progress



28. Infinity swimming pool work in progress



29. Kids swimming pool work in progress



30. Tower A Sub main wire pulling work in progress



PA 5th floor



PA 21st floor



PA 22nd floor



PA 33rd floor



PA 36th floor



PA 39th floor

31. Tower B Sub main wire pulling work in progress



G Floor club house



G Floor club house



PB 3rd floor



PB 9th floor



PB 12th floor



PB 24th floor

32. Tower A 7th floor False ceiling work in progress



33. Tower A 45th floor corridor power meter installation done



34. Tower A 4404 gypsum plaster work in progress



35. Tower B 45th floor Corridor gypsum paster work in progress



36. Tower B 45th floor Corridor ceiling pressure pipe line work in progress



37. Tower B 45th floor Flat entry main door side - wall dado work in progress



38. Quality induction meeting with marble team contractor



39. Safety meeting @ site



40. Tower A : 4 passenger & 1 service lifts

L1 : Lift Ready high-speed completed final adjustment in progress
L2: Lift Ready high-speed completed final adjustment in progress
L3: Lift Ready high-speed completed final adjustment in progress
L4 :Lift in operational
L9 : Service lifts - Entrance door block work completed.
Inside primer work completed, Syncon team work in progress



41. Tower B : 4 passenger & 1 service lifts lifts

L5 : Lift Ready high-speed completed final adjustment in progress
L6 : Lift Ready high-speed completed final adjustment in progress
L7 : Lift Ready high-speed completed final adjustment in progress
L8 : Lift Ready high-speed completed final adjustment in progress
L10 : Service lift- - Entrance door block work completed.
Inside primer work completed, Syncon team work in progress



42. Doors reached at site from 11th floor tower A installation in process



43. Italian marble | Concrete solid blocks | Concrete Cobbles | Granite arrived @ site



TOWER – A (PA)

- **Tiles**

Floor	: 100%	} 99%
Dado	: 100%	
Lift Lobby	: 98%	

- **Windows**

Duct Doors	: 92%	} 71%
Corridor Windows	: 92%	
Lobby windows	: 81%	
Staircase windows	: 90%	
Louvers	: 2%	

- **Gypsum** : 95%

Grand Total

88%

TOWER – B (PB)

- **Tiles**

Floor	: 99%	} 97%
Dado	: 96%	
Lift Lobby	: 92%	

- **Windows**

Duct Doors	: 92%	} 40%
Corridor Windows	: 2%	
Lobby windows	: 19%	
Staircase windows	: 90%	
Louvers	: 0%	

- **Gypsum** : 65%

67%

Due to ongoing works at site and continuous movement of materials within site premises, customer visit to site are not allowed for safety reasons

Customer site visit remains closed till 30th June 2026

THANK YOU.

www.thepresidentialtower.co.in